

Mine Name: Developments 1

Operator Name: Decorative Developments

Inspector(s): Brett Gregory for Leslie Heppler

## State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R STYLER Executive Director JOHN R BAZA
Division Director

## Inspection Report Minerals Regulatory Program

Date: October 28, 2008

	111
Reviewed:	-

Permit Number: S/035/0033 Inspection Date: 10/16/2008

Time: 2:00 pm

Other Participants: None		Mine Status: Active			
		Elements of Inspection	Evaluated	Comment	Enforcement
	L	Permits, Revisions, Transfer, Bonds			
	2.	Public Safety (shafts, adits, trash, signs, highwalls)	$\boxtimes$		
	3.	Protection of Drainages / Erosion Control			
	4.	Deleterious Material			
	5.	Roads (maintenance, surfacing, dust control, safety)			
	6.	Concurrent Reclamation	$\boxtimes$	$\boxtimes$	
	7.	Backfilling/Orading (trenches, pits, roads, highwalls, shafts, drill holes)			
	8.	Water Impoundments			
	9.	Soils			
	10	Revegetation			
	11_	Air Quality			

Bond Amount: \$10,000

12 Other

Permit fee: Current.

Purpose of Inspection: This was a routine annual inspection of the site.

Inspection Summary: Photos attached

6) Difficult to tell the extent of the mining operation that is ongoing from the disturbance of any concurrent reclamation. Concurrent Reclamation is recommended by DOGM

12) The NOI should be updated with current maps that are more representative of disturbance at this site. The contact for this permit is listed as Ben McInnes, Operator needs to update permit if contact person has changed.

<u>Conclusions and Recommendations</u>: An annual mining report is required to be submitted. The boundaries of the mining area need to be clearly defined Defined disturbance should be staked in the field on the ground. DOGM will continue to monitor this site.

Inspector's Signature


BG:vs

cc: Ben McInnes

O:\M035-SaltLiners-0350033-Developments1\Inspection\insp-10162008.mg



Northwest view of disturbance




Equipment used on the premises - view of disturbance.



Operator's Trailer? - view of disturbance

Recent mining extraction - disturbance



Southeast view of north face

North face disturbance